REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave Blank)		3. REPORT TYPE AND DATE	S COVERED
	27 Mar 01		ce Proceeding
4. TITLE AND SUBTITLE			ING NUMBERS
Marine Bacteria and Localized con Effect	rrosion in Polymer Coated St	eel: Cause and Contrac	t No. N00014-94-1-0026
6. AUTHOR(S)			
Brenda J. Little, Richard I. Ray, l	Patricia A. Wagner		
7. PERFORMING ORGANIZATION NA	ME(S) AND ADDRESS(ES)		ORMING ORGANIZATION RT NUMBER
Naval Research Laboratory			2/7333-98-0041
Oceanography Division Stennis Space Center, MS 39529-:	5004	NRL/FI	7/333-70-00+1
9. SPONSORING/MONITORING AGEN	NCY NAME(S) AND ADDRESS(E	S) 10. SPO	NSORING/MONITORING
Office of Naval Research		AGE	NCY REPORT NUMBER
800 N. Quincy St. Arlington, VA 22217-5660			
Armigion, VA 22217-3000			
11. SUPPLEMENTARY NOTES			
Corrosion 99			
Paper No. 183			
12a. DISTRIBUTION/AVAILABILITY S	STATEMENT	12b. DIS	TRIBUTION CODE
Approved for public release, distr	ibution is unlimited		
13. ABSTRACT (Maximum 200 word Diagnosis of microbiologically be based soley on spatial relations experiments were designed to evaluated. In all cases, the distribution independent of coating combination deposits and few bacterial cells. Recoating defects and that attraction cells.	y influenced corrosion on iron hips between large accumulat uate the relationship between of bacteria was strongly influens. In the presence of cathod esults demonstrate that bacter	ions of bacterial cells and iron marine bacteria and localized tenced by the presence of iron ic protection, coating defects ria are preferentially attracted	I corrosion and coated mild corrosion products were filled with calcareous to iron corrosion products in
·	·	20010	808 029
14. SUBJECT TERMS			15. NUMBER OF PAGES
cathodic polarization marine bacte	ria, seawater, mild steel, pol	ymer coatings	8 16. PRICE CODE
47 OFOLIDITY OF A CONTINUE OF	OF CURITY OF A COLUMN	19. SECURITY CLASSIFICATIO	N 20, LIMITATION OF
17. SECURITY CLASSIFICATION 18 OF REPORT	S. SECURITY CLASSIFICATION OF THIS PAGE	OF ABSTRACT	ABSTRACT
Unclassified	Unclassified	Unclassified	SAR
NSN 7540-01-280-5500			Standard Form 298 (Rev. 2-89) Prescribed by ANSI Std. Z39-18

GENERAL INSTRUCTIONS FOR COMPLETING SF 298

The Report Documentation Page (RDP) is used in announcing and cataloging reports. It is important that this information be consistent with the rest of the report, particularly the cover and title page. Instructions for filling in each block of the form follow. It is important to stay within the lines to meet optical scanning requirements.

- Block 1. Agency Use Only (Leave blank).
- Block 2. Report Date. Full publication date including day, month, and year, if available (e.g. 1Jan88). Must cite at least the year.
- Block 3. Type of Report and Dates Covered. State whether report is interim, final, etc. If applicable, enter inclusive report dates (e.g. 10Jan87 30Jun88).
- Block 4. <u>Title and Subtitle</u>. A title is taken from the part of the report that provides the most meaningful and complete information. When a report is prepared in more than one volume, repeat the primary title, add volume number, and include subtitle for the specific volume. On classified documents enter the title classification in parentheses.
- Block 5. Funding Numbers. To include contract and grant numbers; may include program element number(s), project number(s), task number(s), and work unit number(s). Use the following labels:

C - Contract PR - Project
G - Grant TA - Task
PE - Program WU - Work Unit
Element Accession No.

- Block 6. <u>Author(s)</u>. Name(s) of person(s) responsible for writing the report, performing the research, or credited with the content of the report. If editor or compiler, this should follow the name(s).
- Block 7. Performing Organization Name(s) and Address(es). Self-explanatory.
- Block 8. Performing Organization Report
 Number. Enter the unique alphanumeric report
 number(s) assigned by the organization
 performing the report.
- Block 9. Sponsoring/Monitoring Agency Name(s) and Address(es). Self-explanatory.
- Block 10. Sponsoring/Monitoring Agency Report Number. (If known)
- Block 11. Supplementary Notes. Enter information not included elsewhere such as: Prepared in cooperation with...; Trans. of...; To be published in.... When a report is revised, include a statement whether the new report supersedes or supplements the older report.

Block 12a. <u>Distribution/Availability Statement.</u>
Denotes public availability or limitations. Cite any availability to the public. Enter additional limitations or special markings in all capitals (e.g. NOFORN, REL, ITAR).

DOD - See DoDD5230.24, "Distribution Statements on Technical Documents."

DOE - See authorities.

NASA- See Handbook NHB 2200.2.

NTIS - Leave blank.

Block 12b. Distribution Code.

DOD - Leave blank.

DOE - Enter DOE distribution categories from the Standard Distribution for Unclassified Scientific and Technical Reports.

NASA- Leave Blank. NTIS - Leave Blank.

- Block 13. Abstract. Include a brief (Maximum 200 words) factual summary of the most significant information contained in the report.
- Block 14. <u>Subject Terms.</u> Keywords or phrases identifying major subjects in the report.
- Block 15. <u>Number of Pages.</u> Enter the total number of pages.
- Block 16. <u>Price Code.</u> Enter appropriate price code (NT/S only).
- Blocks 17 19. <u>Security Classifications.</u> Self-explanatory. Enter U.S. Security Classification in accordance with U.S. Security Regulations (i.e., UNCLASSIFIED). If form contains classified information, stamp classification on the top and bottom of the page.
- Block 20. <u>Limitation of Abstract</u>. This block must be completed to assign a limitation to the abstract. Enter either UL (unlimited) or SAR (same as report). An entry in this block is necessary if the abstract is to be limited. If blank, the abstract is assumed to be unlimited.

Division, Code

Author, Code

	\$20 9 20 034427 044 1407
	S HER GLEDNER I THE IS LIKE IN NAV

TECHNICAL INFORMATION

Or A-64

	ATION OR PR		ION RELEASE	4103935	NRLINST 5600. MINISTRATIVE INFORMATION
Ref:	b) NRL instruction 5600 b) NRL instruction 5510 1) Two copies of subject).3B).40D	[] Journal article [] Conference pr [Oral presentat [] Meeting [] Other [] Will not result	roceedings	Route Sheet No. PP/733398-0041 Job Order No
4 AUT	OR				dict.
Title of P.	per or Presentation				
				Polymer Coast	ed Steel: Cause and Effect
Author(s)	Name (First, MI, Las	t, Code, Affilia	ation if not NRL)		
Bre	ida Little, Cod	de 7333			
It is inten	led to offer this paper	to the	Corrosion 99	(Name of C	bolamaca)
apr	W25-30,	1999	San Guto	e and Classification of Co	unclassi Jud
and/orfol	publication in	·			
with refer It is the o This pape	ance (a), hinlon of the author the r does not violate and tated to the Laborato	on, pertinent p nat the subject y disclosure of nov in confiden	t paper (is) (s not) plassifi	ata will be entered in ied, in accordance to tions of outside indi	VIGUALS OF COLICERIES AFFICIATION FIGURE
This subi	uct namer (has) (has r	never) been ir	corporated in an official N	VRL Heport.)
This subj	ict paper (has) (has r	never) been ir	ncorporated in an official r	VRL Report.	Drenda Little
This subj	ect paper (has) (has r Brenda J. Litt	never) been ir tle, Çode	ncorporated in an official r	NRL Report.	Drenda Sittle
This subj	ect paper (has) (has r Brenda J. Litt	never) been ir tle, Çode	7333	NRL Heport.	Drenda Little
This subj	Brenda J. Litt	never) been ir tle, Çode	7333	DATE	Drenda Little
This subj	Brenda J. Litt Na ING/APPROVAL	never) been ir tle, Çode	7333 (Principal Author)	VHL Hepoit.	Die da Sotti
This subj	Brenda J. Litt Na ING/APPROVAL CODE Author(s)	never) been ir tle, Çode	7333 (Principal Author)	DATE	Dienda Stelli (Signature)
This subj	Brenda J. Litt Na ING/APPROVAL CODE Author(s)	never) been ir tle, Çode	7333 (Principal Author)	DATE	COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review
S B.	Brenda J. Litt Na ING/APPROVAL CODE Author(s) ittle	never) been ir tle, Çode	7333 (Principal Author)	DATE	COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review completed and release approved as per SECNAVINST
This subj	Brenda J. Litt Na ING/APPROVAL CODE Author(s) ittle anch Head	never) been ir tle, Çode	7333 (Principal Author)	DATE	COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review completed and release
This subj	Brenda J. Litt Na ING/APPROVAL CODE Author(s) ittle anch Head lision Head	never) been ir tle, Çode	7333 (Principal Author)	DATE	(Signature) (Signature) COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review completed and release approved as per SECNAVINST 5720.44A. 1. Release of this paper is approved. 2. To the best knowledge of this Division, the subject matter of this paper (has) that never been classifier
B. B. 733	Brenda J. Litt Na ING/APPROVAL CODE Author(s) ittle anch Head ilision Head ilision Head	never) been ir tle, Çode	7333 (Principal Author)	DATE 10/28/98	COMMENTS COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review completed and release approved as per SECNAVINST 5720.44A. 1. Release of this paper is approved. 2. To the best knowledge of this Division, the subject
S B Pour Public Re Public Re	Brenda J. Little Na ING/APPROVAL CODE Author(s) ittle anch Head ilision Head ilision Review case (Unclassified)	never) been ir tle, Çode	7333 (Principal Author)	DATE 10/28/98	(Signature) COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review completed and release approved as per SECNAVINST 5720.44A. 1. Release of this paper is approved. 2. To the best knowledge of this Division, the subject matter of this paper (has) that never been classified. 1. Paper or abstract was released.
B. SB. This subj	Brenda J. Litt Na ING/APPROVAL CODE Author(s) ittle anch Head ilision Head	never) been ir tle, Çode	7333 (Principal Author)	DATE 10/28/98	(Signature) COMMENTS COMMENTS NOT RELEASABLE UNTIL Security and Policy Review completed and release approved as per SECNAVINST 5720.44A. 1. Release of this paper is approved. 2. To the best knowledge of this Division, the subject matter of this paper (has) that never been classified. 1. Paper or abstract was released.

Paper No. 183



MARINE BACTERIA AND LOCALIZED CORROSION ON POLYMER COATED STEEL: CAUSE AND EFFECT

Brenda J. Little, Richard I. Ray, and Patricia A. Wagner
Naval Research Laboratory
Stennis Space Center, MS 39529

Joanne Jones-Meehan Naval Research Laboratory Washington, DC 20375

C. C. Lee and Florian Mansfeld
Dept. of Materials Science, University of Southern California, Los Angeles, CA 90089

ABSTRACT

Diagnosis of microbiologically influenced corrosion on iron-containing substrata exposed in marine environments cannot be based solely on spatial relationships between large accumulations of bacterial cells and iron corrosion products. Field experiments were designed to evaluate the relationship between marine bacteria and localized corrosion on coated mild steel. In all cases, the distribution of bacteria was strongly influenced by the presence of iron corrosion products independent of coating combinations. In the presence of cathodic protection, coating defects were filled with calcareous deposits and few bacterial cells. Results demonstrate that bacteria are preferentially attracted to iron corrosion products in coating defects and that attraction is more influential than topography in determining the spatial distribution of bacterial cells.

KEYWORDS: cathodic polarization, marine bacteria, seawater, mild steel, polymer coatings

INTRODUCTION

The role that bacteria play in producing/influencing anodic and cathodic corrosion reactions has been documented in the literature on microbiologically influenced corrosion (MIC). However, the impact of anodic and cathodic polarizations on deposition or settlement of bacteria has not been adequately addressed. One of the most serious challenges in identification of MIC is differentiation between biological and abiological processes. Most MIC investigations determine spatial relationships between bacteria and corrosion products using microscopy or microbiological diagnostic kits. Spatial relationships are then interpreted as causal. The reasoning is that because some number of microorganisms traditionally associated with MIC (i.e., sulfate-reducing bacteria {SRB}, metal-depositing or metal-reducing bacteria) and corrosion products are co-located, the microorganisms must have caused the corrosion. Experiments have been designed to evaluate spatial relationships between corrosion products and marine bacteria. Crevices were allowed to form on 304 stainless steel in abiotic seawater with accumulations of corrosion products. [1]

Publication Right

Government work published by NACE International with permission of the author(s). Requests for permission to publish this manuscript in any form, in part or in whole must be made in writing to NACE International, Publications Division, P.O. Box 218340, Houston, Texas 77218-8340. The material presented and the views expressed in this paper are solely those of the author(s) and are not necessarily endorsed by the Association. Printed in the U.S.A.

Marine bacteria were added to the medium and allowed to remain in contact with the corroding specimen for 14 days. At the end of the exposure period, microscopy was used to determine the location of marine bacteria. In all cases, large concentrations of cells were associated with abiotically formed iron corrosion products. The organisms did not cause the corrosion, but were co-located with the iron corrosion products. Interpretation of spatial relationships on polymer coated materials is further complicated because bacteria preferentially colonize surface inhomogeneities including scratches, cracks, and pinholes. [2,3] These same areas are the first to exhibit localized corrosion in abiotic, artificial seawater.

In an attempt to determine the relative importance of topography and iron corrosion products in the spatial distribution of marine microorganisms, field experiments were designed to evaluate relationships between marine bacteria and surface defects in a series of polymer coatings (Table 1) on mild steel. The coatings differed in composition of primer, midcoat, topcoat, and coating thickness. Specimens were exposed with and without zinc anodes to provide cathodic protection. Environmental scanning electron microscopy/energy dispersive x-ray spectrometry (ESEM/EDS) were used to document the presence of cells and determine elemental composition of corrosion products, respectively.

MATERIALS AND METHODS

Panels

Triplicate cold rolled steel panels (10.16 cm × 15.24 cm) were coated with the following combinations: zinc primer and epoxy polyamide topcoat; zinc primer, epoxy polyamide midcoat, and polyurethane topcoat; phosphate primer and epoxy polyamide topcoat; phosphate primer, epoxy polyamide midcoat, and polyurethane topcoat; ion vapor-deposited (IVD) aluminum (Al) primer and epoxy polyamide topcoat; IVD-Al primer, epoxy polyamide midcoat, and polyurethane topcoat; and three layers of epoxy polyamide (Table 1). Panels were exposed with and without intentional defects. Defects were introduced by drilling four 0.32-cm-diameter holes (two per side) 2.54 cm from the bottom edge and 2.54 cm from the side edge (Fig. 1) through the coating to the metal surface to create a defined holiday in the coating. Some panels with intentional defects were cathodically protected by attaching a zinc anode; others were allowed to freely corrode.

Seawater Exposures

Panels were exposed for 30 d to natural seawater at the Key West, FL, Naval Research Laboratory Marine Corrosion Facility and to artificial seawater in laboratory tests. At the end of exposure, panels from the natural seawater exposures were shipped to the Naval Research Laboratory, Stennis Space Center, MS (NRLSSC) in closed, Plexiglas[®] containers filled with natural seawater. Containers were constructed with slots so that multiple panels were secured in the orientation in which they had been exposed to prevent disruption of surface layers. Plexiglas[®] containers were shipped by overnight courier in insulated cartons with ice packs to slow biological activity.

Photodocumentation

Upon arrival at NRLSSC, wet panels were photographed and examined with a Wild Heerbrugg M8 zoom stereo microscope. Areas of interest, including bubbles, holidays, delamination, blisters, corrosion, stains, etc., were photographed with a Polaroid MicroCam attachment using Polaroid type 339 color print film. Panels from the natural seawater exposures were transferred to separate containers of 4% glutaraldehyde in 0.45 µm filtered natural seawater as appropriate and refrigerated overnight. Mild steel panels from laboratory exposures were also transferred to a separate container of 4% glutaraldehyde in artificial seawater and refrigerated overnight. Prior to microscopic examination, each panel was removed from the glutaraldehyde fixative in seawater and gently rinsed in distilled water.

After photography and prior to ESEM examination, areas of interest were carefully cut from wet panels. Smaller wet sections were transferred to a refrigerated Peltier cooling device maintained at 4°C and imaged in a water vapor environment at 4–5 torr in a partially hydrated state. ESEM operating parameters have been described elsewhere. [4]

RESULTS

Seawater Exposures

Metallic zinc and IVD-Al primers (coatings A, B, E, and F) provided cathodic protection for coatings without intentional defects. After 30 days, these coatings were discolored due to the presence of microalgae and macrofouling, but there was no localized corrosion. In the absence of intentional defects, localized corrosion was prominent on surfaces with phosphate primer and the all-epoxy polyamide coatings (coatings C, D, and G). In all cases, delamination was accompanied by localized corrosion and accumulations of bacteria (Fig. 2). In the presence of cathodic protection by an external zinc anode, intentional defects were filled with calcareous deposits (see for example Fig. 3a—c). The EDS spectrum of the calcareous deposits indicates the presence of zinc and phosphate from the primer in addition to calcium. There were no indications of corrosion and the numbers of individual bacterial cells within the defects were similar to the numbers of cells on the intact coating. There were no accumulations of bacteria within any of the defects protected by an external anode.

Coating composition influenced corrosion behavior and location of bacteria in defects without cathodic protection from zinc anodes. Defects in the coatings with zinc primer were, in all cases, filled with calcareous deposits and no corrosion products or accumulations of bacteria were observed. While the zinc primer on steel provided cathodic protection to exposed steel in defects, the same effect was not consistently observed for samples with IVD-Al primer. One of the four panels with IVD-Al primer had no indication of corrosion products in any of the defects, while all others were filled with corrosion products. When corrosion was present, there were accumulations of bacterial cells.

In the absence of cathodic protection provided by an external anode or the primer, most defects in the other coatings were filled with voluminous corrosion products (Fig. 4a-c) and large accumulations of bacteria (Fig. 5a-c). ESEM images were collected from the center of the corroding defect. Large accumulations of bacteria could only be located in association with corrosion products. Even though the specimens were exposed to the same body of seawater, there were morphological differences among the bacteria within defects of various coatings.

DISCUSSION

For the following discussion, the term "coating" will be used to refer to combinations of layers – primer, midcoat, and topcoat. Individual layers will be referred to as "coats." Coatings and cathodic protection are both engineering techniques with the primary purpose of mitigating or preventing corrosion. Cathodic protection reduces corrosion rates by shifting the potential of the corroding material to values where the rate of anodic metal dissolution is reduced. Coatings can be used in combination with cathodic protection. Cathodic potentials promote formation of hydroxyl ions on cathodic areas that forces a shift in the equilibria of chemical reactions involving calcium, magnesium, and bicarbonate ions so that calcium carbonate and magnesium hydroxide are formed in coating breaches.

Primer is the base coat on which the rest of the coating system is applied. Metallic aluminum and zinc can be used as primers to provide corrosion resistance. The inorganic matrix of the primer is conductive and allows aluminum or zinc to go into solution in a controlled manner, making either anodic to the steel and, thus, able to protect breaks in the coating. Eventually holidays, pinholes, scratches, or scars heal by the formation of reaction products, such as zinc hydroxide or calcium carbonate. Intermediate or mid-coats provide additional thickness that acts as a barrier from the environment, increased coating electrical resistance, as well as bonding between topcoat and primer. Topcoats provide resistant seals for the coating, an initial barrier to the environment, and a pleasing appearance.

In the marine exposures, rust layers were accompanied by large concentrations of marine bacteria irrespective of coating composition. There were no indications of corrosion within coating defects that had zinc primer with or without external anodes. In the absence of an anode, defects on samples A and B were filled with crystalline material (Fig. 3a-c) that was predominantly calcium. In the presence of an attached sacrificial zinc anode, defects in all coatings were filled with crystalline material that was predominantly calcium at all locations. Relative amounts of zinc and calcium varied. Furthermore, large concentrations of bacteria could not be detected within defect areas

protected by either zinc as primer or as sacrificial anode. In all other cases, defects were mounded with bright reddish-orange corrosion products (Fig. 4) and large concentrations of marine bacteria (Fig. 5). Tightly coiled helical shapes, typical of some iron-oxidizing bacteria, reportedly rare in the marine environment^[5], were concentrated within the corrosion products on samples C and D with phosphate primer, epoxy polyamide midcoat, and polyurethane topcoat (Fig. 5b). These organisms, in association with mounds or tubercles of iron corrosion products, are often used as indicators of MIC.^[6,7]

Other investigators have observed the co-location of bacteria and anodic processes. Franklin et al. detected bacterial cells associated with anodic regions of carbon steel using scanning vibrating electrode microscopy. [8] They were cautious not to interpret their data to indicate that the cells caused the anodic sites. They did observe that once bacteria were associated with anodic regions, those areas remained anodic for the duration of the experiments. Anodic sites not associated with bacteria were transient. Similar observations of spatial relationships between Oceanospirillum and anodic regions on copper surfaces were made. [9] DeSanchez and Schiffrin demonstrated chemotaxis of a marine Pseudomonas sp. induced by transition metal ion concentration gradients from corroding copper and titanium surfaces. [10] Loeb and Neihof used microelectrophores to demonstrate that particles in the marine environment, including bacteria, are negatively charged and attracted to positive charge. [11]

In our experiments, cathodic protection did not influence the concentration of bacteria within intentional defects. Numerous investigators have demonstrated a relationship between marine fouling and calcareous deposits on cathodically protected surfaces. [12,13] The literature on the relationship between bacteria and cathodic protection is confusing and difficult to compare because of differing experimental conditions (laboratory vs. field) and differing techniques to evaluate the constituents within the biofilm. It has been reported that cathodic protection retards microbial settlement because of the alkaline pH generated at the surface. Dhar [14] demonstrated that a potential more negative than -0.95 V (Cu/CuSO₄) was effective in decreasing bacterial content on titanium in seawater by 1 to 2 orders of magnitude.

Licina^[15] and Angell^[16] independently developed techniques for measuring currents sustained by bacteria that require cathodic polarizations to "encourage biofilm formation."^[15] Nekoksa and Gutherman^[17] and Guezennec^[18] showed that more marine bacteria settled on cathodically protected metals than on unpolarized ones. Gomez de Saravia^[19] and Videla^[20] demonstrated that cathodic polarization in a seawater medium increased numbers of SRB and decreased numbers of aerobic bacteria on carbon steel surfaces relative to unpolarized controls. They hypothesized that preferential increases or decreases in cell types were due to differences in cell isoelectric points.

SUMMARY AND CONCLUSIONS

The distribution of bacteria on coated mild steel with defined defects was strongly influenced by the presence of iron corrosion products independent of coating composition. In natural marine exposures, bacteria were consistently co-located with iron oxide corrosion products. The nature of the attraction has not been identified, but may be related to chemotaxis and/or surface charge. When either a zinc primer or a zinc anode provided cathodic protection, defects were filled with calcareous deposits and contained only isolated bacterial cells, similar to areas of intact coating.

ACKNOWLEDGMENTS

This project was funded by the Office of Naval Research (Dr. A. J. Sedriks) under Contract No. N00014-94-1-0026. Naval Research Laboratory Contribution No. NRL/PP/7303--98-0041.

REFERENCES

- B.J. Little, P.A. Wagner, K.R. Hart, R.I. Ray, "Spatial Relationships Between Bacteria and Localized Corrosion," CORROSION/96, paper no. 278 (Houston, TX: NACE International, 1996).
- 2. P.A. Wagner, B.J. Little, K.R. Hart, R.I. Ray, "Biodegradation of Composite Materials," International Biodeterioration and Biodegradation, pp. 125-132 (1996).

- 3. W.G. Characklis, "Biofilm Process," in: Biofilms, W.G. Characklis, M.C. Marshall (eds.), John S. Wiley & Sons Publishers, New York, NY, (1990), p. 220.
- 4. R.I. Ray, B.J. Little, P.A. Wagner, K.R. Hart, "Environmental Scanning Electron Microscopy Investigations of Biodeterioration," Scanning, 19 (1997): pp. 98-103.
- 5. H.F. Ridgway, B.H. Olson, "Scanning Electron Microscope Evidence for Bacterial Colonization of a Drinking-Water Distribution System," Applied Environmental Microbiology 41 (1981): pp. 274-287.
- 6. R.W. Lutey, "The Detection and Mitigation of Microbiologically Influenced Corrosion in Industrial Process Water Systems," in: Microbiologically Influenced Corrosion in the Oil & Gas Industry, A NACE Techedge Series Program (Houston, TX: NACE International, 1997).
- 7. R.D. Cullimore, "Practical Manual of Groundwater Microbiology," Lewis Publishers, Chelsea, MI, (1992), pp. 68-70.
- 8. M.J. Franklin, D.C. White, H.S. Isaacs, "Pitting Corrosion by Bacteria on Carbon Steel, Determined by the Scanning Vibrating Electrode Technique," Corrosion Science 32 (1991): pp. 945-952.
- 9. B.J. Little, P.A. Wagner, P. Angell, D. White, "Correlation Between Anodic Areas and Oceanospirillum Biofilms on Copper," International Biodeterioration and Biodegradation 37, 3-4 (1996): pp. 159-162.
- 10. S.R. DeSanchez, D.J. Schiffrin, "Bacterial Chemo-Attractant Properties of Metal Ions from Dissolving Electrode Surfaces," Journal of Electroanalytical Chemistry 403 (1996): p. 39.
- 11. G.I. Loeb, R.A. Neihof, "Marine Conditioning Films," in: Applied Chemistry at Protein Interfaces, R.E. Baier (ed.), (Washington, DC: American Chemical Society, 1973), pp. 319-335.
- 12. K. Nisancioglu, P.O. Gartland, T. Dahl, E. Sander, "Role of Surface Structure and Flow Rate on the Polarization of Cathodically Protected Steel in Seawater," Corrosion 43 (1987): pp. 710-718.
- 13. F. Mansfeld, R. Tsai, H. Shih, B. Little, R. Ray, P. Wagner, "Results of Exposure of Stainless Steels and Titanium to Natural Seawater," CORROSION/90, paper no. 109 (Houston, TX: NACE International, 1990).
- 14. H.P. Dhar, "Electrochemical Methods for the Prevention of Microbial Fouling," Plenum Press, NY, p. 593 (1986).
- 15. G.J. Licina, G. Nekoksa, R.L. Howard, "An Electrochemical Method for On-Line Monitoring of Biofilm Activity in Cooling Water Using the BI\GEORGE® Probe," in: Microbially Influenced Corrosion Testing, J.R. Kearns, B.J. Little (eds.), (Philadelphia, PA: ASTM STP 1232, 1994), pp. 118-127.
- 16. P. Angell, J.-S. Luo, D.C. White, "Studies of the Reproducible Pitting of 304 Stainless Steel by a Consortium Containing Sulphate-Reducing Bacteria," Proceedings of the 1995 International Conference on Microbially Influenced Corrosion, (New Orleans, LA: NACE International and American Welding Society, 1995), pp. 1/1-1/10.
- 17. G. Nekoksa, B. Gutherman, "Determination of Cathodic Protection Criteria to Control Microbially Influenced Corrosion in Power Plants," in: Microbially Influenced Corrosion and Biodeterioration, N.J. Dowling, M.W. Mittleman, J.C. Danko (eds.), University of Tennessee (Knoxville, TN: 1991), pp. 6-1-6-8.
- 18. J. Guezennec, "Influence of Cathodic Protection of Mild Steel on the Growth of Sulphate-Reducing Bacteria at 35°C in Marine Sediments," Biofouling 3 (1991): pp. 339-348.
- 19. S.G. Gomez de Saravia, M.F.L. de Mele, H.A. Videla, "Interacciones de Biopeliculas Bacterianas y Compuestos Inorganicos Sobre Aceros Protegidos Catodicamente," in: 5th Congreso Ibero-Americano de Corrosion y Proteccion, D. Grandosa (ed.), (Islas Canarias, Spain: La Laguna, Tenerife, 1995), pp. 201-202.

20. H.A. Videla, S.G. Gomez de Saravia, M.F.L. de Mele,1993"Early Stages of Bacterial Biofilm and Cathodic Protection Interactions in Marine Environments," Proceedings of the 12th International Corrosion Congress (Houston, TX: NACE International, 1993), pp. 3687-3695.

Table 1 — Composition and Thickness of Coating Systems on Cold Rolled Steel.

	, 					5.001.	
Coating	A	В	С	D	Е	F	G
Primer	Zinca	Zinca	Phosphated	Phosphated	IVD-Ale	IVD-Ale	Epoxyf
Midcoat		Epoxy ^b		Epoxy ^b		Epoxy ^b	Epoxyf
Topcoat	Epoxy ^b	Polyurethanec	Epoxy ^b	Polyurthanec	Epoxy ^b	Polyurethanec	Epoxyf
Avg. Thickness (μm)	53	83	43	76	81	81	81
^a 7inc plots							

^aZinc plate per QQ-Z-325 Rev. C (Primer Type II, Class 2).

f 1 coat of MIL-P-24441/2 REV. B epoxy polyamide.





FIGURE 1 — Schematic of panel with intentional defects.

^b2 coats of epoxy polyamide MIL-P-233377 Rev. G (Type I, Class C) per MIL-F-18264 REV. D AMD.1.

^c1 coat of MIL-C-85285 REV. B (AS) AMD.AMD.1.(AR)2 polyurethane per MIL-F-18264REV. D AMD.1 color #36375 lusterless grey of FED-STD-595.

^dPhosphate coat DOD-P-16232 REV. F (Type Z, Class 3); hydrogen embrittlement relieved for 8 minimum hours at 375°F ±/25°F.

^eIon vapor deposited-aluminum per MIL-C-83488-C (Notice 1, Type II, Class 1).








FIGURE 2 — (a) Localized corrosion on panel coated with phosphate primer and epoxy polyamide topcoat (coating C) and (b) bacteria associated with corrosion products.








FIGURE 3 — Zinc primer, epoxy polyamide midcoat, and polyurethane topcoat (coating B): (a) calcareous deposits in defect, (b) ESEM micrograph of calcareous deposits, and (c) EDS spectrum of deposits.




FIGURE 4 — Corrosion products in coating defects, (a) phosphate primer, epoxy polyamide topcoat (coating C), (b) phosphate primer, epoxy polyamide midcoat, polyurethane topcoat (coating D), and (c) three layers of epoxy polyamide (coating G).

FIGURE 5 — Bacteria associated with corrosion products, (a) phosphate primer, epoxy polyamide topcoat (coating C), (b) phosphate primer, epoxy polyamide midcoat, polyurethane topcoat (coating D), and (c) three layers of epoxy polyamide (coating G).